

4.3 CHECKOUT PROCEDURE

(Use the diagram below to verify the outgoing and return PLC communication between the various components.)

This diagram shows how the progress of the signal from the head-end controller to the load can be followed by using the LEDs on each piece of equipment. See Section 4 for an explanation of the LEDs and the diagnostics they provide for the Command Transmitter/Receiver and the Responder.

